



Photo 1 – External front elevation.



Photo 2 – Internal second floor circulation area progress.



Photo 3 – External roof terrace viewed from south looking north left side.



Photo 4 – External roof terrace decked teaching area viewed north.



Photo 5 – External roof terrace front right looking north.



Photo 6 – External roof terrace left side viewed north.



Photo 7 –Internal plant room progress.



Photo 8 – Internal first floor circulation area viewed north.



Photo 9 – Internal first floor circulation area showing light well 1 and 2 progress.



Photo 10 – Internal first floor circulation area showing light well 3.



Photo 11 – Internal first floor circulation area viewed towards north end.



Photo 12 – External rear elevation showing glassed canopy to walkway.



Photo 13 – Internal ground floor circulation area.



Photo 14 – Internal ground floor circulation area.